

## CCTV Survey




Customer	MAURICE CANN	Resource	Martin Reilly
Contact	Maurice Cann		
Address	The Larches, Hutton Road Scotton DL9 3RF	Job type	CCTV Drain Survey
		Reference	DC105451
		Date	24/01/2023 12:30 - 16:30
		Job duration	04:00:00
		Driving duration	00:29:51
		Distance travelled	16.8 mi

Notes Jetting of the lines and CCTV Survey attached are plans - Karin the Daughter 07597803983



Maurice Cann



### 01 Arrival Information

Answer	Notes
Arrival photo - please show working area	 <p>24-01-2023 11:02:33</p> <p>54 353041 - 1 731449</p>

Please state your findings on arrival CCTV survey

### 02 Risk Assessment

	Answer	Notes
Is the working area clear of moving vehicles? If no please enter into the comments what you have put in place to reduce or eliminate the risk using your RAMS in the file library.	Yes	
Is the working area isolated of any members of the public or unauthorised persons? If no please detail in the comments what measure you have put in place to eliminate or reduce the risk following your standard RAMS, which are in the file library.	Yes	

### 03 Risk score

	Answer	Notes
Please rate the risk according to the risk matrix	Low	
Low Statement - please read	STATEMENT READ - If low, please continue with work	

### CCTV Drain Survey

	Answer	Notes
On initial inspection how many visible manholes are there?	3 manholes	
Are there any hidden manholes?	No	
Please describe the surface eg. patio, grass, concrete	Concrete and grass	

Take photo of each manhole (internal and external images if possible). For hidden manholes, take photo of area where manhole is located



Did you find blockages in any lines? If so, which lines and where were the blockages located?

No

How did you clear the blockages?

Na

Are any lines holding water? If so, please explain why and where

No

Did you find any other defects eg. displaced joints?

Yes


What remedial work would you advise and why?

From manhole 01 to manhole 02 there is a hole and fractures in the line at one point. Please see CCTV footage.

Any other advice given to the customer

No

Please upload a copy of your site drawings





---

**Are there any lines you were unable to camera? If so, please state which ones and explain why**

Yes the line from manhole 02 fo manhole 03 because manhole 02 has a Windsor trap and the maintenance point has been cemented up and manhole 03 is seized solid so cant lift it out of the frame.